


AD-A115 645

CONSTRUCTION ENGINEERING RESEARCH LAB (ARMY) CHAMPAIGN IL F/6 11/6
INVESTIGATION OF MATERIALS FOR WATERPROOFING LEAKY CORRUGATED 6--ETC(U)
MAR 82 S M KANAROWSKI
CERL-YR-M-312

UNCLASSIFIED

NL

For
AD-A115 645



END
DATE
FILMED
7-82
DTIC

construction
engineering
research
laboratory




United States Army
Corps of Engineers
... Serving the Army
... Serving the Nation

12
TECHNICAL REPORT M-312
March 1982

INVESTIGATION OF MATERIALS FOR
WATERPROOFING LEAKY CORRUGATED GALVANIZED
STEEL-ARCH MAGAZINES FROM THE INSIDE

by
Stanley M. Kanarowski

DTIC
S ELECTE D
JUN 16 1982




Approved for public release; distribution unlimited.

82 06 16 032

AD A115645

DTIC FILE COPY



The contents of this report are not to be used for advertising, publication, or promotional purposes. Citation of trade names does not constitute an official indorsement or approval of the use of such commercial products. The findings of this report are not to be construed as an official Department of the Army position, unless so designated by other authorized documents.

***DESTROY THIS REPORT WHEN IT IS NO LONGER NEEDED
DO NOT RETURN IT TO THE ORIGINATOR***

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER CERL-TR-M-312	2. GOVT ACCESSION NO. AD-A225	3. RECIPIENT'S CATALOG NUMBER 645
4. TITLE (and Subtitle) INVESTIGATION OF MATERIALS FOR WATERPROOFING LEAKY CORRUGATED GALVANIZED STEEL ARCH MAGAZINES FROM THE INSIDE		5. TYPE OF REPORT & PERIOD COVERED
		6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(s) Stanley M. Kanarowski		8. CONTRACT OR GRANT NUMBER(s) MIPR No. N00025-81-MP-NFA07 MP-81-1
9. PERFORMING ORGANIZATION NAME AND ADDRESS US ARMY CONSTRUCTION ENGINEERING RESEARCH LABORATORY P.O. BOX 4005, Champaign, IL 61820		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
11. CONTROLLING OFFICE NAME AND ADDRESS		12. REPORT DATE March 1982
		13. NUMBER OF PAGES 43
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Copies are obtainable from the National Technical Information Service Springfield, VA 22161		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Magazines (ordnance) waterproofing steel		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) Leaky ammunition storage magazines are a serious problem both because of the deterioration of stored materiel and the high cost of repair. The usual repair procedure for galvanized steel and concrete magazines is to remove the earth cover, clean and waterproof the exterior surface, then replace the earth cover. ↗		

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

Block 20 continued.

This study evaluates materials that can be used to waterproof leaky corrugated galvanized steel magazines from the inside—the most economical approach. While this method has been tried before, it generally has been unsuccessful because of the types of materials used and application procedures.

For this investigation, literature on the subject was reviewed, military installations with steel-arch leakage problems were contacted and remedial methods identified, military installations were visited as required, and 50 manufacturers were contacted for recommendations on sealing and waterproofing materials for galvanized steel magazines. Twenty-eight manufacturers furnished 50 samples of sealants, including new materials, for tests.

A laboratory procedure was developed and equipment designed and made to test the sealants. Three tests were conducted: adhesion-peel on a corrugated galvanized steel sheet, both normal and after water immersion; adhesion compatibility to a butyl rubber gasket; and resistance to hydrostatic pressure.

As a result of these tests 12 satisfactory sealants were identified.

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

FOREWORD

This research was conducted for the Naval Facilities Engineering Command (NAVFAC) under MIPR No. N00025-81-MP-NFA07 and the Directorate of Military Programs, Office of the Chief of Engineers (OCE), under Funding Authorization Document No. MP-81-1, dated 1 October 1980. The work was performed by the Engineering and Materials Division (EM), U.S. Army Construction Engineering Research Laboratory (CERL). Dr. R. Quattrone is Chief of EM. The NAVFAC Technical Monitor was Mr. Howard Nickerson; the OCE Technical Monitor was Mr. Dick Wight, DAEN-MPE-T.

The assistance of Mr. Steven C. Sweeney and Mr. Guy Morrow is acknowledged. Cooperation of the Navy, Army, Marine Corps, and Air Force installation personnel is also heartily acknowledged.

COL L. J. Circeo is Commander and Director of CERL, and Dr. L. R. Shaffer is Technical Director.

Accession For	
NTIS	<input checked="" type="checkbox"/>
DTIC TAB	<input checked="" type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By _____	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A	



CONTENTS

	Page
DD FORM 1473	1
FOREWORD	3
LIST OF TABLES AND FIGURES	5
1 INTRODUCTION	7
Background	
Objective	
Approach	
Mode of Technology Transfer	
2 FIELD INVESTIGATION	7
Review of Literature	
Installation Survey	
Installation Visits	
3 LABORATORY INVESTIGATIONS	8
Sealant Materials	
Laboratory Evaluation Tests	
4 CONCLUSIONS	11
TABLES	11
FIGURES	24
APPENDIX A: Data From Field Investigations	34
APPENDIX B: Sealant Manufacturers Contacted	40
DISTRIBUTION	

TABLES

Number	Page
1 Water Seepage Reported in Corrugated Galvanized Steel-Arch Magazines	11
2 Material Types Recommended by Manufacturers for Waterproofing Leaks in Corrugated Galvanized Steel-Arch Ammunition-Storage Magazines From the Inside	12
3 Results of Adhesion-Peel Test	14
4 Sealant/Butyl Gasket Adhesion Compatibility	17
5 Cost of Successful Sealant Materials for Galvanized Steel	20
6 Sealant Cost Comparison	23
A1 U.S. Army Installations Contacted	34
A2 U.S. Navy and Marine Corps Installations Contacted	36
A3 U.S. Air Force and Other Installations Contacted	38

FIGURES

Number	Page
1 Application of Sealant Over Template on Steel Panel	24
2 Screen Wire Placed on Sealant and Imbedded With Additional Sealant	24
3 Corrugated Galvanized Steel Panel With Sealant Specimens for Normal Adhesion-Peel Test	25
4 Corrugated Galvanized Steel Panel With Sealant Specimens Immersed in Water	25
5 Sealant Specimen Clamped and Pulled With an Attached Spring Scale to Determine Adhesion-Peel Strength	26
6 Sealant Specimen No. 18: Good Adhesion-Peel Strength	26
7 Sealant Specimen No. 38: Good Adhesion-Peel Strength	27
8 Sealant Specimen No. 30: Poor Adhesion to Galvanized Steel	27

FIGURES (cont'd)

Number	Page
9 Sealant Specimen No. 22: Poor Adhesion to Galvanized Steel	28
10 Sealant-Butyl Gasket Adhesion Compatibility Specimens	28
11 Sealants With Good Butyl Gasket Adhesion Compatibility	29
12 Sealants With Poor Butyl Gasket Adhesion Compatibility	29
13 Galvanized Steel Pipe Used for Measuring Resistance of Sealants to Hydrostatic Pressure Leaks	30
14 Three Sets of Holes Made in Pipe for Each Sealant, 19 Sets in Whole Pipe	30
15 Application of Sealant Over Holes in Hydrostatic Pressure Test Pipe	31
16 Hydrostatic Pressure Test Unit With Resistance Wire Heating Attachment	31
17 Hydrostatic Pressure Test Unit Inlet Assembly	32
18 Hydrostatic Pressure Test Unit Outlet Assembly	32
19 Example of Two Sealants Failing in Hydrostatic Pressure Test	33
20 Example of Sealant Failing in Hydrostatic Pressure Test	33

INVESTIGATION OF MATERIALS FOR WATERPROOFING LEAKY CORRUGATED GALVANIZED STEEL-ARCH MAGAZINES FROM THE INSIDE

1 INTRODUCTION

Background

The U. S. Army and Navy have had problems with water seepage in newly constructed and existing earth-covered, steel-arch, ammunition-storage magazines. Repair methods (removal of earth cover and recoating and sealing) are expensive, time consuming, and not always effective.

The Office of the Chief of Engineers (OCE) and the Naval Facilities Engineering Command (NAVFAC) asked the U.S. Army Construction Engineering Research Laboratory (CERL) to investigate the various materials that could be used to waterproof these steel-arch storage magazines from the inside. While standard designs for these structures incorporate elaborate waterproofing schemes, if a leak still occurs, there have been no remedies short of removing the earth cover and starting over.

Objective

The objective of this study was to investigate and evaluate recommended sealant materials (including new materials) for waterproofing leaks on the inside of steel-arch magazines.

Approach

To achieve this objective, CERL:

1. Reviewed the literature on this subject.
2. Contacted military installations with steel-arch leakage problems and identified remedial methods used.
3. Visited military installations as required.
4. Contacted manufacturers for recommendations on inside waterproofing materials for galvanized steel and obtained samples.
5. Developed laboratory tests and equipment, prepared corrugated steel plate sealant adhesion specimens, applied various sealant materials selected

to evaluate their resistance to prolonged hydrostatic load, and obtained information about the cost of materials found acceptable.

Mode of Technology Transfer

Information contained in this report will have a potential impact on Corps of Engineers Basic Drawing 33-15-73 (Oval Steel-Arch), Standard Drawing AW 33-15-64 (Semi-Circular Steel-Arch Magazine as opposed to oval), and Design Guide (DG) 1110-3-70, *Ammunition and Explosive Storage Structures*.

This information will also have a potential impact on NAVFAC Drawing Nos. 1059128 to 1059130, 1059132, 1069906, 1355460, 1355461, "Earth Covered Steel Circular Arch Magazine," and Drawing Nos. 1404026 to 1404034, "Oval Arch Earth Covered Steel Magazine."

2 FIELD INVESTIGATION

Review of Literature

A review of literature on waterproofing problems in galvanized steel magazines and remedial measures used revealed no significant information. The review included searches of the Defense Technical Information Center, the National Technical Information Service, and the Engineering Index.

Installation Survey

Seventeen Army, 17 Navy and Marine Corps, and 7 Air Force and other installations were contacted for information on water seepage in corrugated galvanized steel-arch magazines. Four Army and four Navy installations did not have steel magazines. Of the 13 Army installations with steel magazines, five (38 percent) had leaks mainly at the anchor base or at bolts. Of 13 Navy and Marine Corps installations, eight (61 percent) had leaks through bolts, seams, and at the anchor base.* Three of the eight installations already had repaired their leaks. In the "Air Force and others" group, three installations (43 percent) had leaks; two of the three had completed repair work.

*Some other sources of moisture are excessive condensation and leaks in the end walls. Corrosion posed a problem in some of the dry desert areas (Yuma Proving Ground, for example), as well as in other locations.

The Army installations contacted had about 255 steel magazines of which 52 (20.4 percent) leaked. The Navy and Marine Corps installations had approximately 215 magazines, of which 169 (78.6 percent) leaked, including 32 percent that had already been repaired. The "Air Force and others" group had about 83 magazines, of which 16 (19.2 percent) leaked; 10.8 percent already had been repaired. Table 1 summarizes these findings.

Various simple and complex procedures were used to repair leaks in steel magazines. Attempts were made to seal the inside of the structures, but the materials used proved to be unsatisfactory. Information on types of sealants tried and application techniques used was not generally available. However, some of the sealants were roofing tar, polysulfide, Bitumastic, Thoroseal, asphalt, and plastic cement; one installation thought silicone was satisfactory. Various materials have been used over the earth cover—asphalt hotmix, concrete, gunite, polyethylene sheet nailed down, and caps of bituminous soil cement. Combinations of as many as nine materials have been applied fairly recently over corrugated galvanized steel magazines. About \$37,500 to \$130,000 per magazine has been spent to control leaking. For more details, see Appendix A, Tables A1 through A3. Tables A2 and A3, particularly, indicate the complex systems chosen for exterior treatment of leaky magazines.

Installation Visits

During this study, magazines at two Army installations were examined. Camp Shelby, MS, had 15 corrugated galvanized steel-arch magazines built between 1971 and 1977, all had leaks. Water seepage was primarily at bolts in different areas of the arch. Magazine #6K was empty; during the visit, eight different sealants were applied over the leaky bolt areas, around each of the marked nuts, and over the top of the nuts. The sealants were Chevron CIM TG, Fulaprene 303, Geocel 2000, 3M-1792, Neobon Trowel Cement, Tremco 50V, Tremco 60V, and Mameco Int'l. Vulkem 116. The effectiveness of these applications will be known when the rainy season begins.

The Iowa Army Ammunition Plant (AAP) in Middletown, IA, had both galvanized steel and concrete magazines. Six steel magazines built in 1969 and 1973 were investigated. Leaks were mainly at the anchor bolts that join the corrugated steel sheets to the anchor plate at the concrete base. (The contractor was called back several times before completion of

construction to seal leaks, especially around bolts.) Water seepage was also noted in some of the longitudinal seams. Corrosion and rust were present in a few areas. Drainage troughs were not provided in the floor next to each wall since drainage tile had been installed on the exterior of the concrete bases. One experimental method used at Iowa AAP to solve the seepage problem in steel magazines was to strip off the sod cover of the earth embankment and replace it with a 1/2-in. (12.7-mm)-thick, asphalt-impregnated mat liner to seal the surface. This method has been successful but requires yearly maintenance similar to roofing. A major difficulty is the settling and movement of the earth, which causes the liner to crack.

This investigation, like CERL's work on sealing leaky concrete ammunition storage bunkers, confirmed that outside repairing, though sometimes effective, is expensive and time consuming.¹ Significant maintenance and repair savings are possible if an efficient, reliable inside repair technique can be developed to seal leaking magazines.

3 LABORATORY INVESTIGATIONS

In general, the laboratory investigations consisted of: (1) planning and developing test procedures and techniques; (2) designing testing equipment and purchasing materials and parts for tests; (3) building a multiple-sample hydrostatic test assembly for evaluation of screened sealant materials; (4) obtaining manufacturer-recommended waterproofing materials; (5) application of sealant materials to corrugated galvanized steel panels for adhesion-peel tests, and to the butyl seam gasketing to determine adhesion compatibility; and (6) application of selected sealant materials to the hydrostatic pressure test unit and subjecting the sealants to a pressure test at a hydrostatic pressure that could be expected in the field.

Sealant Materials

About 50 manufacturers were contacted for their recommendations about material that could be used to waterproof leaks in corrugated galvanized steel-arch

¹Stanley M. Kanarowski, *Investigation of Materials for Waterproofing Leaky Concrete Ammunition Storage Bunkers From The Inside*, Special Report M-256/ADA064731 (U.S. Army Construction Engineering Research Laboratory [CERL], January 1979).

magazines. Twenty-eight manufacturers recommended sealants and furnished 50 samples, which fell into two general categories: (1) caulks, sealants, and mastics, and (2) epoxies.

Only flexible materials were selected for final evaluation because of the possibility of movement (settling and thermal) in the magazine structure. Detailed information about the manufacturers and other organizations contacted is given in Appendix B. Table 2 is a generic classification of the sealant materials received and the manufacturers.

Laboratory Evaluation Tests

Laboratory evaluations of sealant materials were conducted in the following order: (1) adhesion-peel—normal and after 1 and 2 weeks of immersion in water, (2) sealant adhesion compatibility with butyl seam gasket—normal and after 1 week of water immersion, and (3) hydrostatic pressure resistance of selected sealants.

Adhesion Peel

Preparation of Corrugated Galvanized Steel Panels for Sealants. The purpose of this test was to screen sealants that adhered poorly to galvanized steel. Sealants with good adhesion would then be tested hydrostatically.

Armco corrugated galvanized steel-arch panels were used as the substrate for sealant application. The three panels were similar to those used for magazine construction. All were No. 1 U.S. Standard Gage, 0.259 in. (6.58 mm) in thickness; two were 33-9/16-in. wide x 10-ft long (0.85 x 3.05 m). One was 52-3/4-in. x 10 ft (1.34 x 3.05 m). Before sealant application, the three steel panels were power wire brushed to remove dirt and any rust or other corrosion products, and were then wiped and cleaned with toluene to remove any grease. The surface seemed fairly smooth.

Application of Sealant Materials to the Steel Panels and Testing. Two sets of duplicate sealant specimens, 3-in. wide x 8-in. long (76 x 203 mm) were applied on a spaced template over the crest of the corrugations of the galvanized steel from valley to valley, one set on each panel (Figures 1 through 4). Aluminum insect screening wire was imbedded in the sealant, which was about 1/4-in. thick (6.35 mm). After curing, the specimens were cut into 1-in.-wide strips (25.4 mm) for pull tests on normal samples and on samples to be immersed in water for 1 and 2 weeks. The whole panel with all the applied samples was immersed.

After curing (on normal specimens), or at the conclusion of immersion in water, the 1-in. (25.4-mm)-wide specimens were clamped in a modified vise-grip locking plier attached to a spring scale and pulled by hand at a steady slow rate until the specimen either pulled off the steel or broke (Figure 5). The highest scale reading in pounds (kilograms) was noted, recorded, and averaged for two specimens of each sealant. Adhesion strength of the sealant to the galvanized steel was rated as follows:

Scale Reading in Lbs, Average	Adhesion Classification
30+	Excellent*—adhesion and sealant strength
20-29	Good*—adhesion and sealant strength
15-19	Fair or spotty (nonuniform adhesion)
1-14	Weak—usually soft sealant
0	Pulls off easily by hand

Table 3 lists the adhesion ratings for all the sealants evaluated.

Adhesion Test Results and Discussion. In the pull test, the soft sealants (low cohesive strength) gave low pull values and were classified as "weak," but adhered to the steel. It took little pull strength to pull them apart. This type of sealant would not be able to resist hydrostatic pressure. Some sealants were strong or tough but did not adhere well. Other sealants held well but pulled loose from the steel at higher pull-pound values. The best sealants in this test had high pull values and good adhesion. A sealant with good adhesion would break or tear at a high pull value and still adhere to the steel. Cohesion would be strong—but weaker than adhesive strength. Figures 6 through 9 illustrate good and poor adhesion to galvanized steel.

The screening wire reinforcement kept the specimens from breaking while being pulled so that a higher stress could be exerted on the sealant/steel adhesion interface.

Sealant/Butyl-Gasket Adhesion Compatibility. In the regular procedure for bolting corrugated steel panels in magazine construction, a gasket sheet is used between the lap splice metal joints. It is normally about 1/8-in. thick x 4-1/4-in. wide (3.2 x 108 mm). Armco 101 Multi-Plate Seam Gasket, for example, is a butyl, cloth-reinforced sheet made by 3M.** After the

*Specimen breaks with no loss of adhesion to the steel.

**3M 1202-T Sealant Tape.

gasket is installed, holes are pierced in the area of the bolt holes, the bolt inserted, and a torque wrench is used to tighten together the panels (150 to 300 ft-lb torque [667 to 1334 N]). Tightening will force the uncured gasket to flow and form a water seal. This process is not always effective, and sometimes voids are left at seams or bolt holes through which the water can leak.

In some cases the material used for sealing the leak may touch the butyl gasket; thus, the sealant's adhesion compatibility with the gasket should be known. Figure 10 shows the specimens used in the visual and hand pull tests for determining the adhesion compatibility between the sealant and the butyl gasket.

This test was conducted by applying the sealant being evaluated to 6-in (152-mm) lengths of 4-1/4-in. (108-mm)-wide gasket. After cure, the sample was cut in half lengthwise, and one specimen was immersed in water for 1 week at room temperature. Specimens were flexed and bent 180 degrees; adhesion, cracking, and color change were noted. Test results are listed in Table 4. Out of 46 sealant specimens in this test, there were 20 with good adhesion and no cracks, eight with bad adhesion, and 18 that were loose at the edge, had cracks, or were soft and tacky. The immersed specimens (1 week) were generally unaffected by the water, but were discolored slightly or looked a bit dirtier. Figures 11 and 12 show good and poor sealant/butyl-gasket adhesion compatibility.

Sealant Materials Selected for Further Testing. On the basis of the adhesion-peel test results, the following sealants were selected for hydrostatic pressure resistance tests:

No.

- 4 Weatherban Sealant 202, 3M
- 5 Weatherban Sealant 404, 3M
- 7 Water Seal 100, Geocel
- 8 Construction 2000 Sealant, Geocel
- 10 Fulaprene 303, H. B. Fuller
- 12 Non-Sag Sealing Compound 12-4, Goodyear
- 13 Scotch Seal Metal Sealant 1792, 3M
- 17 Rubber Calk 7000, PRC
- 18 Vulkem 116, Mameco International
- 19 Sonolastic NPI, Sonneborn-Contech
- 25 Tremproof 60V, Tremco
- 29 Vertiseal, A. C. Horn

- 36 (a) Neobon Trowel Cement with Chloroprime Primer, Atlas Minerals and Chemicals
- 36 (b) Neobon Trowel Cement with Chloroprime and NTC Adhesive, Atlas Minerals and Chemicals
- 37 Chevron CIM-TG, Chevron
- 38 Tremproof 50V, Tremco
- 45 Carboline 163-2 Caulk, Carboline
- 50 Dymeric, Tremco

Resistance of Sealants to Hydrostatic Pressure

Preparation of Test Unit. The equipment designed for measuring the hydrostatic pressure resistance of sealants consisted of a galvanized steel pipe, 4-1/2-in. outside diameter by 10-ft long (114 mm x 3.05 m); see Figure 13. For testing each sealant, the pipe had a combination of a slit and two sets of holes in parallel around the pipe: first was a 1/16-in. x 2-in. slit (1.6 x 51 mm); then two 1/16-in. holes (1.6 mm) with a 3/16-in. hole (4.8 mm) in between, and finally three 1/8-in. holes (3.2 mm); see Figure 14. This combination was repeated on the pipe for 19 sealants although 18 were tested. The nineteenth complete set was sealed off.

After the holes were drilled and the slits cut, the inside of the pipe was cleaned thoroughly by swabbing several times with a rag soaked in toluene. The exterior surface of the pipe was power wire brushed lightly and then wiped and cleaned with toluene to remove any surface grease or oil.

Application of Sealant Materials. Sealants were applied according to the manufacturers' instructions; primers were used when required. Sealant materials in cans or pails were applied with a wooden tongue depressor or spatula. A caulking gun was used for sealants in cartridges. The sealant materials were applied to a nominal 1/4-in. thickness (6.4 mm) and 1-in. width (25.4 mm) centered over the holes, and to 1 in. (25.4 mm) beyond the ends of the slits or the end holes (Figure 15). Specimens were allowed to cure as stated in the manufacturers' specifications, and the water pressure was turned on to 5 to 6 psig (34.5 to 41.4 kN/m²). Pressure was cycled by turning the water off at the end of the workday and on again in the morning. The overnight pressure, however, did not drop to zero but was between zero and the test pressure. This procedure was continued throughout the test. Figure 16 shows a resistance wire attachment for warming the pipe to accelerate curing of the sealants. Figures 17 and 18 show the control ends of the hydrostatic test pipe.

Results of Hydrostatic Pressure Test. Six sealant materials failed within 3/4 to 21 hours of hydrostatic pressure:

	<i>Hours to Failure, Average</i>
Construction 2000 Sealant, Geocel	Less than 1
Water Seal 100, Geocel	Less than 1
Non-Sag Sealing Compound	
12-4, Goodyear	1
Weatherban Sealant 202, 3M	4
Scotch Seal Metal Sealant,	
1792, 3M	16
Weatherban Sealant 404, 3M	21

The remaining 12 sealants resisted hydrostatic pressure for 300 hours at 5 to 6 psig (34.5 to 41.4 kN/m²), followed by 1000+ hours at 7 to 8 psig (48.3 to 55.2 kN/m²). Figures 19 and 20 show sealants that failed the hydrostatic pressure test. Note the stream of water coming out of the leak.

Cost Comparison

Of the 12 sealants which performed satisfactorily in the tests, there were five one-component and seven

two-component types. Tremco Tremproof 60V, a one-component, requires a primer. Five of the two-component sealants require a primer. Four of the one-component sealants are furnished in cartridge containers for application with common caulking guns. Table 5 provides detailed cost information on the successful sealants; for easy reference, Table 6 summarizes costs per gallon.

4 CONCLUSIONS

Laboratory tests indicated that 12 materials can satisfactorily seal leaky corrugated galvanized steel magazines: Fulaprene 303, PRC Rubber Calk 7000, Vulkem 116, Sonolastic NPI, Tremproof 60V, Verti-seal, Neobon Trowel Cement with Chloroprime Primer, Neobon Trowel Cement with Chloroprime and NTC Adhesive, Chevron CIM-TG, Tremproof 50V, Carboline 163-2 Caulk, Dymeric (Table 2). Field tests, using inside sealing techniques, should be done for 2 years to verify the effectiveness of these materials.

Table 1
Water Seepage Reported in Corrugated Galvanized Steel-Arch Magazines

	Army	Navy and Marine Corps	Air Force and Others
Active installations contacted	17	17	7
Installations with galvanized steel magazines	13	13	7
Seepage reported, no. of installations	5 (38%)	5 3* 8 (61%)	1 2* 3 (43%)
Approximate total of steel magazines involved	255	215	83
Leaky magazines	52 (20.4%)	100 (46.5%) 69† (32.1%) 169 (78.6%)	7 (8.4%) 9† (10.8%) 16 (19.2%)

*Installations that already had repaired leaky magazines.

†Leaky magazines that already had been repaired.

Table 2
Material Types Recommended by Manufacturers for Waterproofing Leaks in
Corrugated Galvanized Steel-Arch Ammunition-Storage Magazines From the Inside

Sample No. and Type		Trade Name	Manufacturer
Caulk or Sealant, One-Component Elastomeric			
1	Acrylic	60+ Unicrylic	Pecora
2(a,b,c)*	Butyl	Butyl Caulk ¹	Atlas Minerals & Chemicals
3		Flexiseal CW-100	DAP
4		Weatherban Sealant 202	3M
5		Weatherban Sealant 404	3M
6		BC-158	Pecora
7	Modified Ethylene	Water & Weather Sealant 100	Geocel
8	Copolymer	Construction Caulking Sealant 2000	Geocel
9		Bathroom Caulking Sealant	Geocel
10	Neoprene	Fulaprene 303	H. B. Fuller
11	Nitrile	Self-Leveling Sealant 12-3	Goodyear Tire & Rubber
12		Non-Sag Sealing Compound 12-4	Goodyear Tire & Rubber
13		Scotch-Seal Metal Sealant 1792	3M
14	Styrene Butadiene Rubber	Pinchweld Glass Primer 4584 ²	Tremco
15	Polypropenate	Chem-Calk 800	Woodmont Products
16	Polysulfide	Weatherban Sealant 101	3M
17		PRC Rubber Calk 7000	Products Research & Chemical
18	Polyurethane	Vulkem 116 ³	Mameco International
19		Sonolastic NPI	Sonneborn Div., Contech
20	Silicone	Silicone Rubber Sealant 732 ⁴	Dow Corning
21		Silpruf Weatherproofing Sealant ⁵	General Electric
22		Chem-Calk 1000, Low Modulus ⁶	Woodmont Products
23	Styrene Ethylene- Butylene Block-Copolymer	Plio-Seam Sealant	Goodyear Tire & Rubber
24	Acrylic, Asphalt Extended	No. 26	Al-Chroma
25	Polyurethane, Bitumen Modified	Tremproof 60 Vertical ⁷	Tremco

*Parenthetical letters designate different systems.

¹ a, no primer; b, with Thioment primer; c, Ampvar primer.

² With 200 cleaner.

³ With Cleaner Conditioner.

⁴ With Primer #1200.

⁵ With SCP 3153 Silicone Metal Primer.

⁶ With N-40 Primer.

⁷ With 200 Cleaner and Primer No. 6.

Table 2 (Cont'd)

Sample No. and Type	Trade Name	Manufacturer
Miscellaneous Sealants, One-Component		
26 Proprietary Wax Type Sprayable	Nox Rust 3000	Daubert Chemical
27 Butyl Rubber Adhesive and Sealant Laminated to Soft Aluminum Foil	Alumaflash	Republic Powdered Metals
Caulk or Sealant, Two-Component Elastomeric		
28 Polysulfide	GC-401 Class B Sealing Compound	Goal Chemical Sealants
29	Vertiseal (with primer)	A. C. Horn
30	PRC Rubber Calk 350	Products Research & Chemical
31	H-705 Gray Sealant	Steelcote Manufacturing
32	#126-188 Gray Sealant	Steelcote Manufacturing
33(a,b,c,d) Polyurethane	Polytok-Deck Coating 131/522 ⁸	Carboline
34	Coating 132-82	Steelcote Manufacturing
35	Sealant 132-84	Steelcote Manufacturing
Mastic-Type Sealants, Two-Component Elastomeric		
36 (a,b,c) Neoprene Base	Neobon Trowel Cement ⁹	Atlas Mineral & Chemicals
37 Polyurethane, Asphalt Extended	Chevron Industrial Membrane Trowel Grade (CIM-TG) ¹⁰	Chevron U.S.A.
38 Polyurethane, Bitumen Modified	Tremproof 50V ¹¹	Tremco
Epoxy-Sealants, Two-Component*		
39 Epoxy-Modified Aliphatic Amine	Concresive AEX-1438	Adhesive Engineering
40	Concresive AEX-1459	Adhesive Engineering
41	46-X-3/46-T-6 Epoxy Liner	Mobil Chemical
42	Sikastix 360, Sikadur Lo-Mod Gel	Sika Chemical
43 Epoxy-Modified Polyamido Amine	Epi-Rez 510/Epi-Cure 892	Celanese Plastics & Specialties

⁸Used as furnished, then added #2400 Silica to increase viscosity. Also used with Primer CE, or with Wash Primer 1037 followed by CE.

⁹With Chloroprime, or Chloroprime and Neobon Trowel Cement Adhesive, or Ampvar Primer and Neobon Trowel Cement Adhesive.

¹⁰With Bonding Agent Primer.

¹¹With 200 Cleaner and Primer No. 6.

*Except No. 50, which is three-component.

Table 2 (Cont'd)

Sample No. and Type	Trade Name	Manufacturer
44	Epi-Rez 510/Epi-Cure 892/24-219	Celanese Plastics & Specialties
45	Epoxy-Polyamide	Carboline
46	A-788 Splash Zone Compound	Koppers
47	46-X-16 Epoxy Patching Compound	Mobil Chemical
48	Epoxy-Polyamine	Aquatopoxy
49	Epoxy-Polysulfide	Caulking Compound 225
50	Epoxidized Polyurethane Terpolymer	Dymeric ¹² , 3-Component
		Tremco

¹² Use with 200 Cleaner and Primer No. 6.

Table 3
Results of Adhesion-Peel Test

Sample No.	Caulk or Sealant	Normal	After Water Immersion		Comment
			1 Week	2 Weeks	
One-Component Elastomeric					
1	60+ Unicrylic (Pecora)	Weak	Weak, pulled off	Weak, pulled off	Soft sealant
2(a,b,c)	Butyl Caulk ¹ (Atlas)	Weak Sealant is soft and has low cohesive strength	Weak	Weak	3 without or with primers
3	Flexiseal CW-100 (DAP)	Pulled off metal completely			
4	Weatherban 202 (3M)	Weak	Pulled off at 28 lb*	Pulled off at 40 lb	
5	Weatherban 404 (3M)	Spotty	Spotty to good	Pulled off at 35 lb	
6	BC-158 (Pecora)	Weak Sealant is soft and has low cohesive strength	Weak	Weak	
7	Sealant 100 (Geocel)	Good	Good	Excellent	
8	Sealant 2000 (Geocel)	Good	Excellent	Excellent	
9	Bathroom Caulking (Geocel) Sealant	Good	Good	Excellent	
10	Fulaprene 303 (H. B. Fuller)	Excellent	(Good to Excellent)		

¹ a, no primer; b, with Thioment primer; c, Ampvar primer.

*1 lb = 0.454 kg.

Table 3 (Cont'd)
Results of Adhesion-Peel Test

Sample No.	Caulk or Sealant	Normal	After Water Immersion		Comment
			1 Week	2 Weeks	
11	Sealant 12-3 (Goodyear)	Pulled off metal		(No specimens)	Self-leveling
12	Sealant 12-4 (Goodyear)	Spotty	Good	Good	
13	Metal Sealant 1792 (3M)	Excellent	Good	Good to excellent	
14	Pinchweld Glass Primer ² (Tremco) #4584	Pulled off metal		(No specimens)	
15	Chem-Calk 800 (Woodmont)	Weak Sealant is soft and has low cohesive strength	Weak	Weak	Soft and sticky
16	Weatherban 101 (3M)	Spotty	Good	Good	Soft and sticky
17	Rubber-Calk 7000 (PRC)	Good	Good to excellent, spotty adhesion	Excellent, spotty adhesion	
18	Vulkem 116 ³ (Mameco Int'l.)	Excellent	Excellent	Excellent	
19	Sonolastic NPI (Sonneborn-Div.)	Weak	Good to excellent, spotty adhesion	Good to excellent, spotty adhesion	
20	Silicone 732 ⁴ (Dow Corning)	Good	Weak, spotty adhesion	Weak	Affected by water
21	Silpruf ⁵ (General Electric)	Excellent	Excellent, spotty adhesion	Pulled off at 20 lb	Affected by water
22	Chem-Calk 1000 ⁶ (Woodmont)	Pulled off at 3 lb	Pulled off	Pulled off at 5 lb	
23	Plio-Seam (Goodyear)	Pulled off	Pulled off	No specimen	
24	No. 26 (Al-Chroma)	Pulled off at 15 and 30 lb	Pulled off at 10 lb	Pulled off at 20 and 28 lb	
25	Tremproof 60V ⁷ (Tremco)	Excellent	Excellent	Excellent	

²With 200 cleaner.

³With Cleaner Conditioner.

⁴With Primer #1200.

⁵With SCP 3153 Silicone Metal Primer.

⁶With N-40 Primer.

⁷With 200 Cleaner and Primer No. 6.

Table 3 (Cont'd)

Sample No.	Caulk or Sealant	Normal	After Water Immersion		Comment
			1 Week	2 Weeks	
26	Too thin a material (self-leveling); must be nonsag-type.				
27	Alumaflash (Republic Powdered Metals)	Weak, material broke	---	---	Adhesion was good
Two-Component Elastomeric					
28	GC-401 Class B (Goal Chemical)	Excellent	Pulled off at 25 lb	Pulled off at 25 and 35 lb	Affected by water
29	Vertiseal (with primer) (A. C. Horn)	Good to excellent All had some areas of weak adhesion	Good to excellent	Good to excellent	
30	Rubber Calk 350 (PRC)	Weak, pulled off	Pulled off at 13 and 20 lb	Pulled off at 30 lb	
31	H-705 (Steelcote)	Viscosity too low Not for vertical applications			
32	126-188 (Steelcote)	Weak, pulled off	Weak, pulled off	Pulled off at 25 lb	
33(a)	131/522 ⁸ (Carboline)	Viscosity too low Not for vertical applications			No added filler
33(b)	131/522 ⁸ (Carboline)	Viscosity too low Not for vertical applications			Added 20% of total wt-Silica Flour
33(c)	131/522 ⁸ (Carboline)	Good	Spotty adhesion	Pulled off at 20 lb	Added 45% of total wt-Silica Flour, used primer CE
33(d)	131/522 (Carboline)	Good	Good	Good	With 45% of total wt-Silica Flour, Primers 1037 and CE
34	132-82 Ctg (Steelcote)	Viscosity too low Not for vertical applications			
35	132-84 (Steelcote)	Pulled off	Good but spotty adhesion	Pulled off at 30 lb	
36(a)	Neobon T. C. ⁹ (Atlas)	Excellent	Good to excellent	Excellent, pulled off at 55 lb	With Chloroprime Primer
36(b)	Neobon T. C. ⁹ (Atlas)	Excellent, spotty adhesion	Weak to excellent	Good to excellent	With Chloroprime and NTC adhesive
36(c)	Neobon T. C. ⁹ (Atlas)	Pulled off at 15 and 20 lb	Pulled off at 25 lb	Pulled off at 22 lb	With Ampvar Primer and NTC adhesive

⁸Used as furnished, then added #2400 Silica to increase viscosity. Also used with Primer CE, or with Wash Primer 1037 followed by CE. See "Comment."

⁹With Chloroprime, or Chloroprime and Neobon Trowel Cement Adhesive, or Ampvar Primer and Neobon Trowel Cement Adhesive. See "Comment."

Table 3 (Cont'd)

Sample No.	Caulk or Sealant	Normal	After Water Immersion		Comment
			1 Week	2 Weeks	
37	CIM TG ¹⁰ (Chevron)	Excellent	Good to excellent	Excellent	With bonding agent primer
38	Tremproof 50V ¹¹ (Tremco)	Excellent	Good to excellent	Excellent	With cleaner and primer
Two-Component Epoxy					
48	Aquatapoxy (American Chemical)	Pulled off easily	Pulled off easily	-----	
49	Caulking Compound 225 (Carboline)	Weak— pulled off at 6 lb	Pulled off at 15 lb	Pulled off at 15 lb	
50	Dymeric ¹² (Tremco)	Excellent	Good to excellent	Good to excellent	With cleaner and primer

¹⁰With Bonding Agent Primer.¹¹With 200 Cleaner and Primer No. 6.¹²Use with 200 Cleaner and Primer No. 6.Table 4
Sealant/Butyl Gasket Adhesion Compatibility

Sample No.	Caulk or Sealant	Normal	Immersed 1 Week	Comment
1	60+ Unicrylic (Pecora)	Flexible, no cracks. Good adhesion.	Same as normal except slight (sl.) color change.	Good
2(a)	Butyl Caulk (Atlas)	Flexible, no cracks. Good adhesion.	Same as normal except dirtier color.	Sticky and soft
3	Flexiseal CW-100 (DAP)	Flexible, no cracks. Good adhesion.	Same as normal except some color change.	Good
4	Weatherban 202 (3M)	Flexible, no cracks. Good adhesion.	Same as normal except some color change.	Tacky and soft
5	Weatherban 404 (3M)	Flexible, no cracks. Good adhesion.	Same as normal.	Tacky and sl. soft
6	BC-158 (Pecora)	Flexible, no cracks. Good adhesion.	Same as normal except some color change.	Soft
7	Sealant 100 (Geocel)	Flexible, no cracks. Good adhesion.	Same as normal except sl. yellowing.	Good
8	Sealant 2000 (Geocel)	Flexible, no cracks. Good adhesion.	Same as normal except sl. yellowing.	Good
9	Bathr. Caukg. Sealant (Geocel)	Flexible, no cracks. Good adhesion.	Same as normal except sl. yellowing.	Good

Table 4 (Cont'd)

Sample No.	Caulk or Sealant	Normal	Immersed 1 Week	Comment
10	Fulaprene 303 (H. B. Fuller)	Flexible, no cracks. Good adhesion.	Same as normal except duller finish.	Good
11	Sealant 12-3 (Goodyear)	Flexible, no cracks. Good adhesion.	Same as normal except sl. darker and tendency to pull loose at edge.	Tendency to pull loose at edge
12	Sealant 12-4 (Goodyear)	Flexible, no cracks. Adhesion not good.	Same as normal except sl. darker.	Adhesion not good
13	Metal Sealant 1792 (3M)	Flexible, no cracks. Adhesion good.	Same as normal except sl. darker.	Good
14	Pinch weld Glass Primer (Tremco) #4584	Flexible, no cracks. Adhesion good.	Same as normal.	Tacky
15	Chem-Calk 800 (Woodmont)	Flexible, no cracks. Adhesion not good.	Same as normal except sl. color change.	Adhesion not good
16	Weatherban 101 (3M)	Flexible, no cracks. Adhesion not good.	Same as normal except some color change.	Adhesion not good
17	Rubber-Calk 7000 (PRC)	Flexible, no cracks. Adhesion good.	Same as normal except sl. color change.	Good
18	Vulkem 116 (Mameco Int'l.)	Flexible, no cracks. Good adhesion.	Same as normal except sl. color change.	Good
19	Sonolastic NPI (Sonneborn-Div.)	Flexible, no cracks. Good adhesion.	Same as normal except sl. color change.	Good
20	Silicone 732 (Dow Corning)	Flexible, no cracks. Adhesion not good.	Same as normal except sl. color change.	Adhesion not good
21	Silpruf (General Electric)	Flexible, no cracks. Adhesion not good.	Same as normal except sl. darker.	Adhesion not good
22	Chem-Calk 1000 (Woodmont)	Flexible, no cracks. Adhesion not good.	Same as normal except sl. darker.	Adhesion not good
23	Plio-Seam (Goodyear)	Flexible, no cracks. Adhesion not good.	Same as normal except sl. darker.	Adhesion not good
24	No. 26 (Al-Chroma)	Flexible, no cracks. Good adhesion.	Same as normal.	Good
25	Tremproof 60V (Tremco)	Flexible, no cracks. Good adhesion.	Same as normal.	Good, sl. tacky
26	Too thin a material (self-leveling); must be non-sag type.			
27	Alumaflash (Republic Powdered Metals)	Flexible, foil cracks. Adhesion good.	Same as normal except no foil cracks.	Foil Cracks
28	GC-401 Class B (Goal Chemical)	Flexible, no cracks. Good adhesion.	Same as normal except sl. darker.	Good

Table 4 (Cont'd)

Sample No.	Caulk or Sealant	Normal	Immersed 1 Week	Comment
29	Vertiseal (A. C. Horn)	Flexible, no cracks. Good adhesion.	Same as normal except sl. color change.	Good
30	Rubber Calk 350 (PRC)	Flexible, no cracks. Good adhesion.	Same as normal except dirtier color.	Good
31	H-705 (Steelcote)	Flexible, no cracks. Adhesion not good.	Same as normal except sl. color change.	Adhesion not good
32	No sample			
33(b)	131/522 (Carboline)	Flexible, no cracks but tendency. Good adhesion.	Same as normal.	Cracking tendency
34	132-82 Ctg. (Steelcote)	Flexible, no cracks. Sl. tendency to pull loose at edge.	Same as normal.	Tendency to pull loose at edge
35	132-84 (Steelcote)	Flexible, get sl. cracks at edge where folded. Adhesion not good at cracks.	Same as normal.	Get fold cracks.
36(a)	Neobon T. C. (Atlas)	Flexible, no cracks. Good adhesion.	Same as normal.	Good
37	CIM-TG (Chevron)	Flexible, no cracks. Good adhesion.	Same as normal.	Good
38	Tremproof 50V (Tremco)	Flexible, no cracks. Good adhesion.	Same as normal.	Good
39	Concr.-AEX-1438 (Adh. Engrg.)	Cracks, brittle. Good adhesion.	Same as normal. Tendency to pull off. Sl. color change.	Cracks
40	Concr.-AEX-1459 (Adh. Engrg.)	Flexible but get edge tears. Good adhesion.	Same as normal except sl. darker.	Edge tears
41	Too thin in viscosity			
42	Sika 360, S.Lo-Mod Gel (Sika)	Some flexibility but cracks. Good adhesion.	Brittle, cracked, otherwise like normal.	Cracks
43	510/892 (Celanese)	Cracks on bending. Brittle. Good adhesion.	Same as normal.	Cracks
44	Too thin in viscosity			
45	Carboline 163-2 (Carboline)	Brittle, cracks on bending. Good adhesion.	Same as normal except sl. duller color.	Cracks

Table 4 (Cont'd)

Sample No.	Caulk or Sealant	Normal	Immersed 1 Week	Comment
46	A-788 (Koppers)	Brittle, cracks easily. Good adhesion.	Same as normal except loss in gloss.	Cracks
47	46-X-16 (Mobil)	Brittle, cracks on folding. Good adhesion.	Same as normal but color not as shiny.	Cracks
48	Aquatapoxy (American Chemical)	Flexible, no cracks. Good adhesion.	Same as normal. Sl. dirtier color.	Good
49	Caulking Compound 225 (Carboline)	Flexible but cracks. Good adhesion.	Same as normal except sl. darker.	Cracks
50	Dymeric (Tremco)	Flexible, no cracks. Good adhesion.	Same as normal except dirtier color.	Good

Table 5
Cost of Successful Sealant Materials for Galvanized Steel*

Bulk Cost Per Gallon**					
Caulk or Sealant	Order Size***	1-Gal Pail	2-Gal Pail	5-Gal Pail	55-Gal Drum
One-Component					
10. H. B. Fuller	1-5 cases: \$3.01/cartridge ⁺	--	--	(1-5) \$19.04/gal	(1-5) \$17.48/gal
Fulaprene 303 (FOB Grand Rapids, MI)	6-10 cases: \$2.78/cartridge ⁺	--	--	(6-10) \$17.57/gal	(6-10) \$16.14/gal
	11-39 cases: \$2.54/cartridge ⁺	--	--	(11-39) \$16.11/gal	(11-39) \$14.79/gal
18. Mameco Inter- national	Under 500 gal: \$2.07/cartridge	(1-500) \$16.95	(1-250) \$16.75/gal	(1-100) \$16.30/gal	(1-9) \$15.50/gal
Vulkem 116 (FOB Cleveland, OH)	Over 500 gal: \$1.97/cartridge	(500+) \$16.05	(250+) \$15.90/gal	(100+) \$15.40/gal	(10+) \$14.65/gal
Cleaner-Conditioner		\$1.85/qt; \$7.35/gal			
17. PRC Rubber Calk 7000 (FOB Glendale, CA)	1-49 gal: \$2.12/cartridge	--	(1-49) \$19.53/gal	(1-49) \$19.53/gal	--
19. Sonneborn- Contech Sono- lastic NPI (FOB Chicago, IL)	\$2.25/cartridge ⁺⁺	--	\$20.00/gal	--	--

*Does not include shipping or cleanup solvents.

**Manufacturers' variations in these sizes are noted for specific materials.

***Cartridges usually have 11 fl oz.

⁺24 cartridges/case.

⁺⁺30 cartridges/case.

Table 5 (Cont'd)

		Bulk Cost Per Gallon**			
Caulk or Sealant	Order Size	1-Gal Pail	2-Gal Pail	5-Gal Pail	55-Gal Drum
25. Tremco Tremproof 60V (FOB Ware- house)	Under \$500 order No. of gallons	--	--	\$11.90-\$12.25/gal 1-42; 1-40	--
	\$500-\$1499 order No. of gallons	--	--	\$10.65-\$11.00/gal 47-140; 46-136	--
	\$1500+ order No. of gallons	--	--	\$9.50-\$9.85/gal 158+; 153+	--
	Plus 200 Cleaner	Any size order \$16.05-\$16.55	--	--	--
	Plus Primer No. 6	Under \$500 order \$34.85-\$35.35 (1-14 gal) Over \$500 order \$31.50-\$32.00 (16+ gal)	--	--	--
38. Tremco		Available only in 4-gal units			
Tremproof 50V (FOB Warehouse)	Under \$500 order	--	--	\$12.10-\$12.45/gal (1-45 gal)	--
	\$500-\$1499 order	--	--	\$11.00-\$11.35/gal (48-140 gal)	--
	\$1500+ order	--	--	\$10.65-\$11.00/gal (141+ gal)	--
Plus 200 Cleaner	Any size order	\$16.05-\$16.55	--	--	--
Plus Primer No. 6	Under \$500 order	\$34.85-\$35.35 (1-14 gal)	--	--	--
	Over \$500 order	\$31.50-\$32.00 (16+ gal)	--	--	--
Three-Components					
50. Tremco Dymeric (FOB Warehouse)	Under \$500 order No. of units, 1-1/2 gal		\$28.37-\$28.93/gal 1-14	--	--
	\$500-\$1499 order No. of units, 1-1/2 gal		\$22.57-\$23.13/gal 15-52	--	--
	\$1500+ order No. of units, 1-1/2 gal		\$19.10-\$19.67/gal 53+	--	--
Plus Color Pak Carton contains 5 Paks; \$8.50, \$7.50, or \$6.50, depending on order size. One Pak used per 1-1/2-gal unit = \$1.70, \$1.50, \$1.30. Max. = \$1.70/unit					

**Manufacturers' variations in these sizes are noted for specific materials.

Table 5 (Cont'd)

		Bulk Cost Per Gallon**			
Caulk or Sealant	Order Size	1-Gal Pail	2-Gal Pail	5-Gal Pail	55-Gal Drum
Plus 200 Cleaner	Any size order	\$16.05-\$16.55			
Plus Primer No. 6	Under \$500 order	\$34.85-\$35.35 (1-14 gal)			
	Over \$500 order	\$31.50-\$32.00 (16+ gal)			
Two Components					
36(a). Atlas Minerals and Chemicals Neobon Trowel Cement (NTC) (FOB Mertz- town, PA)	Any size order	\$56.00	--	\$52.00/gal	--
Plus Chloro- prime	Any size order (About 63+ gal of NTC for every gallon of Chloroprime)	\$26.50	--	\$26.00/gal	--
36(b). Atlas Minerals and Chemicals Neobon Trowel Cement (NTC) (FOB Mertz- town, PA)	Any size order	\$56.00	--	\$52.00/gal	--
Plus Chloro- prime	Any size order (About 63+ gal of NTC for every gallon of Chloroprime)	\$26.50	--	\$26.00/gal	--
Plus NTC Adhesive	Any size order (About 31+ gal of NTC for every gallon of NTC Adhesive)	\$29.00	--	--	--
45. Carboline 163-2 (FOB Xenia, OH)	Volume discount possible	--	--	\$33.25/gal (15-gal kit)	--
37. Chevron CIM-TG (FOB Oakland, CA)	--	--	--	\$12.15/gal (4-1/2-gal unit)	--
Plus Bonding Agent (Each 4-1/2-gal unit of CIM-TG contains 4 gal of Premix and 1/2 gal of Activator.)		--	--	\$7.80/gal	--

**Manufacturers' variations in these sizes are noted for specific materials.

Table 5 (Cont'd)

Caulk or Sealant	Order Size	Bulk Cost Per Gallon**			
		1-Gal Pail	2-Gal Pail	5-Gal Pail	55-Gal Drum
29. A. C. Horn Vertiseal Plus Primer (FOB Addison, IL)	--	\$36.00/gal (3/4 gal unit; includes Vertiseal Primer)	--	--	--

**Manufacturers' variations in these sizes are noted for specific materials.

Table 6
Sealant Cost Comparison*

Caulk or Sealant	Cost. \$/Gal	Components	Primer Needed
37. Chevron CIM-TG	12.15 + bending agent	2	Yes
25. Tremco Tremproof 60V	11.90-12.25 + primer	1	Yes
38. Tremco Tremproof 50V	12.10-12.45 + primer	2	Yes
18. Mameco Int'l., Vulkem 116	16.30 + cleaner/conditioner	1	Cleaner/Conditioner
10. H. B. Fuller, Fulaprene 303	17.57	1	None
17. PRC Rubber Calk 7000	19.53	1	None
19. Sonneborn-Sonolastic NPI	20.00	1	None
50. Tremco Dymeric	28.37-28.93 + 1.70 max. + primer	3	Yes
45. Carboline 163-2	33.25	2	None
29. H. C. Horn, Vertiseal	36.00 (primer included)	2	Yes
36(a) & 36(b). Atlas Min. Chem., Neobon T.C.	52.00 + primer + NTC adh	2	Yes (2 systems)

*In order of increasing cost, limited to intermediate gallon quantities, FOB plant or warehouse. Cost of cleaners not included since they are needed for all sealants.



Figure 1. Application of sealant over template on steel panel.



Figure 2. Screen wire placed on sealant and imbedded with additional sealant.




Figure 3. Corrugated galvanized steel panel with sealant specimens for normal adhesion-peel test.



Figure 4. Corrugated galvanized steel panel with sealant specimens immersed in water.



Figure 5. Sealant specimen clamped and pulled with an attached spring scale to determine adhesion-peel strength.



Figure 6. Sealant specimen No. 18: good adhesion-peel strength.




Figure 7. Sealant specimen No. 38: good adhesion-peel strength.




Figure 8. Sealant specimen No. 30: poor adhesion to galvanized steel.




Figure 9. Sealant specimen No. 22: poor adhesion to galvanized steel.



Figure 10. Sealant-butyl gasket adhesion compatibility specimens.



Figure 11. Sealants with good butyl gasket adhesion compatibility.



Figure 12. Sealants with poor butyl gasket adhesion compatibility.




Figure 13. Galvanized steel pipe used for measuring resistance of sealants to hydrostatic pressure leaks.




Figure 14. Three sets of holes made in pipe for each sealant, 19 sets in whole pipe.



Figure 15. Application of sealant over holes in hydrostatic pressure test pipe.




Figure 16. Hydrostatic pressure test unit with resistance wire heating attachment.



Figure 17. Hydrostatic pressure test unit inlet assembly.




Figure 18. Hydrostatic pressure test unit outlet assembly.




Figure 19. Example of two sealants failing in hydrostatic pressure test. Note water streams.




Figure 20. Example of sealant failing in hydrostatic pressure test.

APPENDIX A

DATA FROM FIELD INVESTIGATIONS

Table A1
U.S. Army Installations Contacted

Installation	Location	Water Seepage Problems	Contact
1. Air National Guard	Peoria, IL	None. Changed building plan. No galvanized steel magazines scheduled.	COL Ballow, 309-697-6400.
2. Anniston Army Depot	Anniston, AL	Have four small earth-covered steel magazines built in late 1960s. Three have leaks at anchor base. Water runs on floor.	Bill Camp or Carl Pace, 205-238-7501, x7515 or 6151, respectively.
3. Badger Army Ammunition Plant	Baraboo, WI	Have 14, built on grade about 1975, not earth-covered. No leaks. Previously used Galvanoleum (Rustoleum Corp.) and Al-Chroma #40 asbestos-aluminum asphalt roof coating. Magazines were rectangular.	Bill Clement and Chuck Mensik, 608-356-5525.
4. Camp Shelby	Hattiesburg, MS	Have 15 built in 1971-77. All have water seepage primarily at bolts. Eight sealants are now under test in one magazine, under CERL recommendation.	MAJ R. Johnson, 601-545-2871, x2683; MAJ Holly Piner, 601-545-2871, x2690.
5. Fort Bragg	NC	Have 33 earth covered, 1956 construction. If have heavy rains for a day or two there is no problem. No major water leakage.	Fred Reeves, Chief of Buildings and Structures. 919-396-7908
6. Fort Carson	CO	Have two built in 1978. No leakage. Dry climate. Have problem with doors. They are hard to operate. Has a better design idea for doors.	Dave Nicholson, 303-579-3513.
7. Fort Leonard Wood	MO	Have eight earth covered built about 1978. Had no leaks when contacted. Rainfall was low. Used silicone sealant at one time on inside, and it was satisfactory. Majority of leaks were at the base where metal was embedded. Has a better idea on the ventilation system. Condensation is excessive.	Gene A. Pahlmann, FTS 270-2510.
8. Fort Polk	LA	Have 20 or 21, WW II type (1940). 95 percent of them leak. Can't tell if leaking through seam or bolt. Tried roofing tar on inside but it didn't work. Expect large expansion in FY83.	Robert Morgan, FTS 495-2911, x4806.
9. Iowa Army Ammunition Plant	Middletown, IA	Have six structures eight and twelve years old, and a few others. Inactive at present. All earth covered. Used polysulfide sealant at leaky bolts and seams at concrete base.	Mr. D. L. Pranger, 319-753-7502.
10. Letterkenny Army Depot	Chambersburg, PA	No regular steel magazines. Use Butler-type buildings. These are on grade and not earth covered; made of corrugated galvanized steel or aluminum. There are no reports of leakage.	Duane Peacock, Michael Myers, 717-263-6111. FTS 591-3810.

Table A1 (Cont'd)

Installation	Location	Water Seepage Problems	Contact
11. Longhorn Army Ammunition Plant	Marshall, TX	Have eight built before 1976. Three are earth covered and five are on grade. No water seepage problem. Rainfall is heavy at times.	Dale Hall, 214-679-2544.
12. Louisiana Army Ammunition Plant	Shreveport, LA	Have 25, two built in 1969, 23 in 1973. No water seepage. In 1976 had water in seam area due to mastic coating improperly applied.	William Sheppard 318-459-5199.
13. Red River Army Depot	Texarkana, TX	No steel magazines. Have only concrete and these were leaky. Outside work on re-water-proofing 20 igloos completed 3 months ago at cost of \$9126 each. May do same work on 44 more.	Wiley Rood, 214-838-2673; Stewart McDonald, 214-838-3245.
14. Redstone Arsenal	Huntsville, AL	No steel magazines. Have eight "Lane Catecombs" test cells made from drainage culvert material built 1966-67. They are 5 1/2 ft tall.	Harbel Lawson, FTS 876-5055.
15. Sunflower Army Ammunition Plant	De Soto, KS	Have eight, built in 1980, and all leak. Contractor instructed not to use them. Also have a condensation problem. May try a 1- to 2-in. urethane foam application on inside if approved. Area is munition sensitive.	Jim Daly, 913-843-3800, x343.
16. Tooele Army Depot	Tooele, UT	Have 72, contract started in 1978. Have problems with head walls and proper grounding. Not much rainfall. All covered on outside with Keeperkote M1 or Perma-gard.	B. L. McIntyre and Dennis Bingham, 801-833-2515 and 2115 respectively.
17. Yuma Proving Ground	Yuma, AZ	Have 44 built from 1950 to 1975. Leaks present no problem. They are of short duration. Soil is high in salt content and corrosion is bad. The 10-to-15-year old magazines are being abandoned since they aren't structurally safe. Five-year-old magazines had inadequate cathodic protection. Corrosion is mostly at ridge, middle, and ceiling at top.	Willard Robinson, 602-328-2151.

Table A2
U.S. Navy and Marine Corps Installations Contacted

Installation	Location	Water Seepage Problems	Contact
1. Marine Corps Base	Camp Pendelton, CA	In one area, four out of 13 steel magazines leaked. Two years ago had heavy rains; there were leaks in seams and around bolts. Bolts could not be tightened. Tried Bitumastic on inside but this didn't work. Decided to work on outside; no contract yet. Have leaks only when it rains hard. The climate is generally dry.	M. Rekdahl, FTS 892-4626.
2. Marine Corps Air Station	Yuma, AZ	Have 12, completed in July 1976. No water problems or corrosion. Corrosion is possible from the salt. Soil cover is stabilized with hot-mix, soil is sandy. Thinks that gunite with joints would work better over the earth cover than asphalt hot-mix. Thinks cathodic protection used in steel plate for protection from salt.	Leroy Lindamood, 602-726-2808.
3. Naval Air Station	Alameda, CA	Have steel magazines. Would not say how many. Have no water seepage. Do have condensation.	Ensign Jerry Richardson, 415-869-4731.
4. Naval Air Station	Brunswick, ME	Have four built in 1943. Moved three to another location about 3 mi away. They were partially dismantled. Exterior surface was painted with asphalt-aluminum paint after scraping and wire brushing. There are no leaks; none of the four has ever leaked. One is near a swampy area and gets some groundwater but no leaks through seams or at bolts.	Dick Gould, 207-921-2445.
5. Naval Air Station	Cecil Field, FL	Have 40 steel magazines completed in 1978. Still working on waterproofing. Not all serviceable yet. Original roof construction consisted of 4 ft of soil over bare metal then 6 in. of concrete; one slab over 20 magazines. Water banked up between magazines and went through bolt holes and seams. New system (modification) consisted of removing the concrete on the top and placing a polyethylene film (10 mils thick) over the metal then soil and sodding. Drainage pipes put between magazines. No leakage since June 1980.	Bill Wilson, 904-778-5620.
6. Naval Air Station	Norfolk, VA	Have 16 steel magazines. Constructed two groups of eight each with a common head wall with magazines side by side under the same berm. Dirt fill is between magazines. Completed in 1978; Moved in during 1981. Developed 4-ft head of water between magazines. This caused leakage at bottom of steel arch. Tried two-component sealant, but this did not help. Roof construction had a 6-mil polyethylene film over the steel. This was covered with earth a minimum of 2 ft. Presently have leakage at anchor base and too much condensation.	LT J. M. Cain 804-444-1364; Ray Margeson, Gunner's Mate Technician Chief, 804-444-4533, or FTS 954-4533, FTS 954-1364.

Table A2 (Cont'd)

Installation	Location	Water Seepage Problems	Contact
7. Naval Air Station	North Island, CA	Have 40 steel magazines completed 1980, built in three stages. Had many leaks. First set had no coating on outside, second set had brittle coating, and third had PVC liner on top and no coating--ground rods pushed through liner. Remedy: (1) Uncovered all 40 to metal, (2) cleaned and primed with asphaltic material, (3) applied Systemized SP11, 90 mils on outside and a gravel layer, (4) filter blanket protective put over top and sides, (5) coarse gravel then put over, 6 to 8 in., (6) another filter blanket, and (7) back filled to 1 ft then 6 in. of gravel and 6 in. clay. Did water test before back filling and after. No leaks. Completed in April and good so far. Note: before priming, all bolts and seams caulked with butyl rubber sealant. Cost \$1.5 million. Includes 4-in. perforated drains on each side of magazines on the outside.	Larry Lind, 415-377-7410.
8. Naval Air Station	Willow Grove, PA	Have two steel magazines 20 ft x 40 ft, have leaks in both (built about 1943). Have water seepage along foundation and due to condensation. Rusting metal is deteriorating. Cleaned the magazines, caulked them, and painted. Problem is still there.	Mr. Rocco Stella, 215-443-1000.
9. Naval Ordnance Station	Indian Head, MD	No steel-arch magazines. Have only reinforced concrete. Vary in age from WW II to recent.	Tim Rath, FTS 364-4844.
10. Naval Submarine Base, New London	Groton, CT	Have 25 steel magazines built in 1971-72. Water was seeping in through bolts. Tried to tighten but couldn't tighten all. Eroded soil replaced and 6 in. of sand, then a Dacron supported chlorinated polyethylene liner was put on. Liner is held in valleys with round boulders 6 in. and less in size. The liner was installed on 20 magazines in 1975. A 5-in. cap of bituminous soil cement is placed over the liner to stabilize soil. Cap is 10 ft x 12 ft and is centered over the crown of each magazine. Fourteen of the magazines are arranged in a row containing seven magazines placed back to back. One liner goes over all 14 magazines. One liner is also placed over the six magazines. There are no leaks.	Mike Murphy, FTS 644-3941.
11. Naval Under Sea War Engineering Station	Keyport, WA	Do not have steel magazines. Have \$0.5 million project for repairing cracks in concrete magazines by epoxy resin injection.	Bob Aske, Les Baker, 206-396-2411.
12. Naval Weapons Center	China Lake, CA	Have 17 steel magazines or 34 if include small ones. Built in early 1940s and 1950s. Have problem with soil erosion. Asphalt coating becomes exposed and deteriorates from sun. Too costly to eliminate. They push more dirt on top. This is a dry desert area.	Jerry Brooks, 714-939-3411.

Table A2 (Cont'd)

Installation	Location	Water Seepage Problems	Contact
13. Naval Weapons Station	Charleston, SC	Have five large and 10 small steel magazines. All leaked. Cover was stripped on four of the five and 2-in. shotcrete applied on outside, then a heavy polyethylene liner, 2-ft minimum earth fill, then 2 in. of hot mix asphalt paving over the earth. This was tried in 1976 on one, then on three more in 1978. Performance is excellent. No evidence of leakage. Inside repairs were tried, but didn't work. Thoroseal, asphalt and plastic cement were used. On the small magazines, a bituminous roof coating was used, 4-in. of stone base then paved with 2-in. of hot asphalt. Cost for this work including drains was \$100,000 in 1976 and \$130,000 in 1978 per magazine. Work was done in a maximum security area.	Dave Lovett, 803-743-7626. FTS 679-7626.
14. Naval Weapons Station	Concord, CA	Have 37 steel magazines just built. Had many leaks at bolts and seams. Now in process of re-doing whole exterior similar to job done at North Island. Cost may run to \$2.3 million for all 37 magazines. See item 7 for North Island data.	Dave Brown, 415-877-7402.
15. Naval Weapons Station, Earle	Cof's Neck, NJ	Have only concrete magazines. 99 percent are 40 years old. No major problems.	Bill Osborne, 201-462-9500.
16. Naval Weapons Station	Seal Beach, CA	No steel magazines.	Jim Orrico, 213-594-7011.
17. Mayport Naval Base	Mayport, FL	Have four steel magazines built in 1970-71. No water seepage although rainfall is heavy, about 50 in. per yr. All built in a swamp. Four concrete igloos are being built currently.	Gunther Houck 904-246-5235 Clyde Bradley, 904-246-5184.

Table A3
U.S. Air Force and Other Installations Contacted

Installation	Location	Water Seepage Problem	Contact
1. Blytheville, AFB,	AK	Have three steel magazines. Leaked when rained. Water came in through seams. Remedy: stripped vegetation, applied 6 mil Visqueen over soil, then 1-1/2-in. gunite, chicken wire 2-in. mesh, and finally 1-1/4 in. of gunite; no earth cover. Gunite used on front walls after joints sealed. Now third summer since work done and results are good. Last year had a few shrinkage cracks in gunite and these were sealed with SC70 cutback asphalt. Thinks they got payback now because of less maintenance.	Ray Clouse, 501-762-7000; Tom Talley, 501-762-7000.
2. Robins AFB,	GA	Have seven standard size and 4 of class A, B, and C. The seven were built in February 1980. These are not earth covered. All seven have leaks at channel iron anchor joint. Civil engineering department will decide what to do.	Rex Kent, FTS 286-4444, direct; 912-926-4444. Claude Adams, FTS 286-5168, direct; 912-926-5168.

Table A3 (Cont'd)

Installation	Location	Water Seepage Problem	Contact
3. Warren AFB	Cheyenne, WY	Have three steel magazines probably built in mid 1972. No leakage that he is aware of. They are in good condition. Climate is dry, about 17 in. of rain per year.	Reuben Altergott, 307-775-3909. Dick Riddell, 307-775-2438 or 2759.
4. Air Defense Command	Walla Walla, WA	Have six steel magazines, not earth-covered, built in early 1960's. No leakage complaints. In good condition. Rainfall is a bit heavy, about 40 in. per year.	Ray Tyrrell, FTS 442-5485; Doug Winn, FTS 442-5500, 509-529-0843.
5. Allegheny Ballistics Laboratory	Cumberland, MD	Have six steel Government magazines and contractor (Hercules) has 18 cubicles, 12- to 15-ft wide x 12-ft high at several different lengths. These were all built in the last 10 years. The Government magazines leaked initially and were cleaned off and redone. Now there is condensation but no leakage. The cubicles had minor leaks originally but none now. They are maintained at 158° to 180° F inside. Tried urethane foam inside and outside; liked outside better.	Bill Lang, 304-726-4500, x8107 Michael Cunningham, 304-726-4500, x8003.
6. Pantex Plant	Amarillo, TX	Have 50 to 60 steel magazines; there is no leakage. These were built 3 to 18 years ago. Asphalt roofing cement and 45-lb asphalted roofing felt put over bolts and seams. More of the roofing cement placed on edges then ground cover. On some, Gulf Seal sheets used on earth cover for erosion control (nailed down). End of Gulf Seal is buried. No drain tile used inside or outside. Have a lot of wind, but rainfall is only 20 in. annually.	Jerry Pennington, 806-335-1581, x2281. FTS 572-2281, direct. Bill Colvin, FTS 738-7011.
7. McDonnell Douglas	Huntington, CA	Have three steel magazines; all shipped to Idaho in last year. They were built 5 years ago. Condition today is good. These were made of 10-gage not 1-gage steel. They were sealed with a bitumen coating on the outside. The base was caulked with asphalt. Rainfall is only about 22 to 25-in. annually.	Bob Goethe, FTS 798-2000, 714-896-1481.

APPENDIX B:

SEALANT MANUFACTURERS CONTACTED

Manufacturers Who Recommended Materials and Furnished Samples

Elastomeric Sealants

1. Al-Chroma, Incorporated
P.O. Box 226
Stevens Point, WI 54481
(715) 344-4691 and 344-4696
Mr. Virgil Peters
2. Atlas Minerals & Chemicals, Inc.
Farmington Road
Mertztown, PA 19539
(215) 682-7171
Mr. Donald G. Reinert
3. Carboline
350 Hanley Industrial Court
St. Louis, MO 63144
(314) 644-1000
Mr. Paul Litzinger
4. Chevron U.S.A, Inc.
Asphalt Division
575 Market St.
San Francisco, CA 94105
(415) 894-4400
Mr. J. E. Henry
5. Dap Inc.
Subsidiary of Plough, Inc.
Dayton, OH 45401
(513) 253-7152
Mr. Ward Treat
6. Daubert Chemical Co.
1200 Jorie Blvd.
Oak Brook, IL 60521
(312) 986-4600
Mr. Scott Lucas
7. Dow Corning Corp.
P.O. Box 1767
Midland, MI 48640
(517) 496-4000 and 800-248-2345
Mr. Bud Smith
8. H. B. Fuller Company
5220 Main Street N.E.
Minneapolis, MN 55421
(612) 560-4350
(800) 328-7307
Mr. James Collins
9. General Electric Co.
Silicone Product Division
Waterford, NY 12188
(518) 237-3330
Mr. Jim Brower
10. Geocel Limited, Inc.
P.O. Box 398
Elkhart, IN 46515
(219) 264-0645
Mr. Robert Sherellis
11. Goal Chemical Sealants Corp.
3137 East 26th Street
Los Angeles, CA 90023
(213) 269-0461
Mr. Marvin Smith
12. Goodyear Chemicals
Ashland, OH
(419) 289-9588
Mr. Ron Lenhard
Dist: W. J. Ruscoe Company
483 Kenmore Blvd.
Akron, OH 44301
(216) 253-8148
Mr. Ed Mobley
13. A. C. Horn, Inc.
1555 Wrightwood Court
Addison, IL 60101
(312) 629-4243
Mr. Victor Weber
14. Mameco International
Vulkem Sealants Division
4475 East 175th Street
Cleveland, OH 44128
(216) 752-4400
Dr. R. B. Greene
15. 3M Company
Adhesives, Coatings and Sealers Division
223-6NE, 3M Center
St. Paul, MN 55101
(612) 733-6999
Mr. Dale Smestad

16. Pecora Corporation
165 Wambold Road
Harleysville, PA 19438
(215) 723-6051
Mr. Al Kilchesty or Glen Holmes

17. Products Research and Chemical Corp.
PRC Coating and Sealants Division
5454 San Fernando Road
Glendale, CA 91203
(213) 240-2060
Mr. Roger Cournoyer

18. Republic Powdered Metals
2628 Pearl Road
Medina, OH 44256
(216) 225-3192
Mr. Dan Struger

19. Sonneborn Building Products
Division of Contech Inc.
7711 Computer Avenue
Minneapolis, MN 55435
(612) 835-3434
Mr. Al Galin

20. Steelcote Manufacturing Co.
3418 Gratiot St.
St. Louis, MO 63103
(314) 771-8053
Mr. Herbert Rosenblatt

21. Tremco
10701 Shaker Blvd.
Cleveland, OH 44104
(216) 229-3000
Mr. Sanford Wohl

22. Woodmont Products, Inc.
County Line and New Roads
P.O. Box 8
Huntington Valley, PA 19006
(215) 357-0755
Mr. Kirt Zintner

Epoxy Sealants

23. Adhesive Engineering Co.
1411 Industrial Road
San Carlos, CA 94070
(415) 592-7900
Ms. Claudia Clark

24. American Chemical Corp.
81 Encina Ave.
Palo Alto, CA 94301
(415) 327-5210
Mr. Bill Warner

25. Carboline
350 Hanley Court
St. Louis, MO 63144
(314) 644-1000
Mr. Paul Litzinger

26. Celanese Plastics & Specialties Co.
One Riverfront Plaza
Louisville, KY 40202
(502) 585-8078
Mr. Jack Avery

27. Koppers Company, Inc.
Organic Materials Group
1900 Koppers Building
Pittsburgh, PA 15219
(412) 227-2000
Mr. Mike Carvlin

28. Mobil Chemical Company
Maintenance and Marine Coatings Dept.
901 North Greenwood Avenue
Kankakee, IL 60901
(815) 933-5561
Mr. Bob Waldrop

29. Sika Chemical Corporation
Box 297
Lyndhurst, NJ 07071
(201) 933-8801
Mr. Steve Sidler

Other Manufacturers Contacted

30. Colorado Chemical Specialties, Inc.
4295 McIntyre St. Dept. 25
Golden, CO 80401
(303) 278-1963

31. Copolymer Rubber and Chemical Corp.
P.O. Box 2591
Baton Rouge, LA 70821
(504) 355-5655

32. Dayton Coatings and Chemical Division
Whittaker Corp.
P.O. Box 27
West Alexandria, OH 45381
(513) 839-4612
(513) 835-5656
33. DuPont Co.
Chemical, Dyes and Pigments Dept.
1007 Market St.
Wilmington, DE 19898
(302) 774-2421
34. Effective Building Products, Inc.
2950 Metro Drive, Suite 305
Minneapolis, MN 55420
(612) 854-3588
Bryan M. McGroarty
35. General Tire and Rubber Co.
Industrial Products Division
One General St.
Wabash, IN 46992
(219) 563-1121
36. Gibson-Homans Co.
1755-T Enterprise Pky.
Twinsburg, OH 44087
(216) 425-3255
37. Hughson Chemicals
2010 W. Grandview Blvd.
P.O. Box 1099
Erie, PA 16512
(814) 868-3611
38. Inmont Corp.
1133 Ave. of Americas
New York, NY 10036
(212) 930-1300
St. Louis, MO (314) 577-1100
39. Master Builders
Div. of Marietta Corp.
23700-T Chagrin Blvd.
Cleveland, OH 44122
(216) 831-5500
40. Mobay Chemical Corp.
Plastics and Coatings Div.
Penn-Lincoln Pky, W.
Pittsburgh, PA 15205
(412) 777-2000
41. Olin Corp.
Winchester-Western Div.
275 Winchester Ave.
New Haven, CT 06504
(203) 777-7911
Olin Research Center
(203) 789-5773
42. Petrarch Systems, Inc.
Box 141-A
Levittown, PA 19059
(215) 638-0490
43. Rust-Oleum Corp.
11 Hawthorn Pkwy.
Vernon Hills, IL 60061
(312) 367-7700
44. Shell Chemical Co.
One Shell Plaza
Houston, TX 77001
(713) 241-6161
Shell Development Co.
(713) 493-7171
45. K. T. Snyder Co.
9601 West Tidwell
Houston, TX 77041
(800) 231-4549
(713) 462-8536
46. Thiokol Corp., Specialty Chemicals Div.
930 Lower Ferry Rd.
Box 8296
Trenton, NJ 08650
(609) 396-4001
47. Union Carbide Corp.
Old Ridgebury Rd.
Danbury, CT 06817
(203) 794-2000
(203) 794-2665

48. United Gilsonite Laboratories
1396 Jefferson Ave.
Scranton, PA 18501
(717) 344-1202

50. Weatherguard Marbleoid Products, Inc.
2515 Newbold Ave.
Bronx, NY 10462
(212) 828-8300

49. U.S. Gypsum Co.
101 S. Wacker Dr.
Chicago, IL 60606
(312) 321-4000
(312) 694-2070
Research Center
(312) 299-3381

CERL DISTRIBUTION

Chief of Engineers
ATTN: Tech Monitor
ATTN: DAEN-ASL-L (2)
ATTN: DAEN-CCP
ATTN: DAEN-CM
ATTN: DAEN-CME
ATTN: DAEN-CM-R
ATTN: DAEN-CWO
ATTN: DAEN-CWP
ATTN: DAEN-MP
ATTN: DAEN-MPC
ATTN: DAEN-MPE
ATTN: DAEN-MPO
ATTN: DAEN-MPR-A
ATTN: DAEN-RD
ATTN: DAEN-RDC
ATTN: DAEN-RDM
ATTN: DAEN-RM
ATTN: DAEN-ZC
ATTN: DAEN-ZCE
ATTN: DAEN-ZCI
ATTN: DAEN-ZCM
ATTN: DAEN-MPE-T (10)
FESA, ATTN: Library 2206U

US Army Engineer Districts

ATTN: Library
Alaska 99501
Al Batn 09616
Albuquerque 87103
Baltimore 21203
Buffalo 14207
Charleston 29402
Chicago 60604
Detroit 48231
Far East 96301
Fort Worth 76102
Galveston 77550
Huntington 25721
Jacksonville 32232
Japan 96343
Kansas City 64106
Little Rock 72203
Los Angeles 90053
Louisville 40201
Memphis 38103
Mobile 36628
Nashville 37202
New Orleans 70160
New York 10007
Norfolk 23510
Omaha 68102
Philadelphia 19106
Pittsburgh 15222
Portland 97208
Riyadh 09038
Rock Island 61201
Sacramento 95814
San Francisco 94105
Savannah 31402
Seattle 98124
St. Louis 63101
St. Paul 55101
Tulsa 74102
Vicksburg 39180
Walla Walla 99362
Wilmington 28401

US Army Engineer Divisions

ATTN: Library
Europe 09757
Huntsville 35007
Lower Mississippi Valley 39180
Middle East 09038
Middle East (Rear) 22601
Missouri River 68101
New England 02154
North Atlantic 10007
North Central 60605
North Pacific 97208
Ohio River 45201
Pacific Ocean 96858
South Atlantic 30303
South Pacific 94111
Southwestern 75202

US Army Europe

HQ, 7th Army Training Command 09114
ATTN: AETTG-DEM (5)
HQ, 7th Army ODGS/Engr. 09403
ATTN: AEAER-EN (4)
V. Corps 09079
ATTN: AETVDEM (5)
VII. Corps 09154
ATTN: AETSDEM (5)
21st Support Command 09325
ATTN: AEREN (5)
Berlin 09742
ATTN: AERBA-EN (2)
Southern European Task Force 09166
ATTN: AESE-ENG (3)
Installation Support Activity 09403
ATTN: AEMES-OP

8th USA, Korea

ATTN: EAFE (B) 96301
ATTN: EAFE-Y 96358
ATTN: EAFE-ID 96224
ATTN: EAFE-AM 96208
ATTN: EAFE-M 96271
ATTN: EAFE-P 96259
ATTN: EAFE-T 96212

416th Engineer Command 60623

ATTN: Facilities Engineer

USA Japan (USARJ)

Ch. FE Div. AJEN-FE 96343
Fac Engr (Honshu) 96343
Fac Engr (Okinawa) 96331

ROR/US Combined Forces Command 96301

ATTN: EUSA-MHC-CFC/Engr

US Military Academy 10996

ATTN: Facilities Engineer
ATTN: Dept of Geography & Computer Science
ATTN: OSCPER/MAEN-A

Engr. Studies Center 20315

ATTN: Library

AMMRC, ATTN: DRXMR-ME 02172

USA ARRCOM 61299

ATTN: DRCIS-R1-1
ATTN: DRSAR-IS

DARCOM - Dir., Inst. & Svcs.

ATTN: Facilities Engineer
ARRADCOM 07801
Aberdeen Proving Ground 21005
Army Mater. and Mechanics Res. Ctr.
Corpus Christi Army Depot 78419
Harry Diamond Laboratories 20783
Dugway Proving Ground 84022
Jefferson Proving Ground 47250
Fort Monmouth 07703
Letterkenny Army Depot 17201
Natick R&D Ctr. 01760
New Cumberland Army Depot 17070
Pueblo Army Depot 81001
Red River Army Depot 75501
Redstone Arsenal 35809
Rock Island Arsenal 61299
Savanna Army Depot 61074
Sharpe Army Depot 95331
Seneca Army Depot 14541
Tobyhanna Army Depot 18466
Tooele Army Depot 84074
Watervliet Arsenal 12189
Yuma Proving Ground 85364
White Sands Missile Range 88002

DLA ATTN: DLA-WI 22314

FORSCOM

FORSCOM Engineer, ATTN: AFEN-FE
ATTN: Facilities Engineer
Fort Buchanan 00934
Fort Bragg 28307
Fort Campbell 42223
Fort Carson 80913
Fort Devens 01433
Fort Drum 13601
Fort Hood 76544
Fort Indiantown Gap 17003
Fort Irwin 92311
Fort Sam Houston 78234
Fort Lewis 98433
Fort McCoy 54656
Fort McPherson 30330
Fort George G. Meade 20755
Fort Ord 93941
Fort Polk 71459
Fort Richardson 99505
Fort Riley 66442
Presidio of San Francisco 94129
Fort Sheridan 60037
Fort Stewart 31313
Fort Wainwright 99703
Vancouver Bks. 98660

HSC

ATTN: HSLQ-F 78234
ATTN: Facilities Engineer
Fitzsimons Army Medical Center 80240
Walter Reed Army Medical Center 20012

INSCOM - Ch. Instl. Div.

ATTN: Facilities Engineer
Arlington Hall Station (2) 22212
Vint Hill Farms Station 22186

MDW

ATTN: Facilities Engineer
Cameron Station 22314
Fort Lesley J. McNair 20319
Fort Myer 22211

MTMC

ATTN: MTMC-SA 20315
ATTN: Facilities Engineer
Oakland Army Base 94626
Bayonne NJT 07002
Sunny Point NJT 20461

NARADCOM, ATTN: DRDMA-F 07160

TARCOM, Fac. Div. 48090

TECUM, ATTN: DRSTE-LG-F 21005

TRADOC

HQ, TRADOC, ATTN: ATEN-FE
ATTN: Facilities Engineer
Fort Belvoir 22060
Fort Benning 31905
Fort Bliss 79916
Carlisle Barracks 17015
Fort Chaffee 72902
Fort Dix 08640
Fort Eustis 23604
Fort Gordon 30905
Fort Hamilton 11252
Fort Benjamin Harrison 46216
Fort Jackson 29207
Fort Knox 40121
Fort Leavenworth 66027
Fort Lee 23801
Fort McCallan 36205
Fort Monroe 23651
Fort Rucker 36362
Fort Sill 73503
Fort Leonard Wood 65473

TSARCOM, ATTN: STSAS-F 63120

USACC

ATTN: Facilities Engineer
Fort Huachuca 85613
Fort Ritchie 21719

WESTCOM

ATTN: Facilities Engineer
Fort Shafter 96858

SHAPE 09055

ATTN: Survivability Section, UCB-UPS
Infrastructure Branch, LANUA

HQ USEUCOM 09128

ATTN: ECJ 4/7-LUE

Fort Belvoir, VA 22060

ATTN: ATZA-DTE-EM
ATTN: ATZA-DTE-SM
ATTN: ATZA-FE
ATTN: Engr. Library
ATTN: Canadian Liaison Office (2)
ATTN: INR Library

Cold Regions Research Engineering Lab 03755

ATTN: Library

ETL, ATTN: Library 22060

Waterways Experiment Station 39180

ATTN: Library

HQ, XVIII Airborne Corps and 28307

Ft. Bragg

ATTN: AFZA-FE-EE

Chanute AFB, IL 61800

3345 CES/DE, Stop 27

Norton AFB 92409

ATTN: AFRCR-MX/DEE

NCEL 93041

ATTN: Library (Code LOBA)

Tyndall AFB, FL 32403

AFESC/Engineering & Service Lab

Defense Technical Info. Center 22314

ATTN: DDA (12)

Engineering Societies Library 10017

New York, NY

National Guard Bureau 20310

Installation Division

US Government Printing Office 22304

Receiving Section/Depository Copies (2)

EMC Team Distribution

Chief of Engineers 20314
ATTN: DAEN-MPO-B
ATTN: DAEN-MPZ-A
ATTN: DAEN-MPR (2)
ATTN: DAEN-ZCP

US Army Engineer District
New York 10007
ATTN: Chief, Design Br
Pittsburgh 15222
ATTN: Chief, ORPCD
ATTN: Chief, Engr Div
Philadelphia 19106
ATTN: Chief, NAEEN-D
Baltimore 21203
ATTN: Chief, Engr Div
Norfolk 23510
ATTN: Chief, NAEEN-M
ATTN: Chief, NAEEN-D
Huntington 25721
ATTN: Chief, ORHED-F
Wilmington 28401
ATTN: Chief, SAMCO-C
ATTN: Chief, SAMEN-D
Charleston 29402
ATTN: Chief, Engr Div
Savannah 31402
ATTN: Chief, SASAS-L
Jacksonville 32232
ATTN: Const Div
Mobile 36628
ATTN: Chief, SAMEN-D
ATTN: Chief, SAMEN-F
ATTN: Chief, SAMEN
Nashville 37202
ATTN: Chief, ORNED-F
Memphis 38103
ATTN: Chief, Const Div
ATTN: Chief, LMED-D
Vicksburg 39180
ATTN: Chief, Engr Div
Louisville 40201
ATTN: Chief, Engr Div
Detroit 48231
ATTN: Chief, NCEED-T
St. Paul 55101
ATTN: Chief, ED-D
ATTN: Chief, ED-F
Chicago 60604
ATTN: Chief, NCCCO-C
ATTN: Chief, NCCED-F
Rock Island 61201
ATTN: Chief, Engr Div
ATTN: Chief, NCRED-F
St. Louis 63101
ATTN: Chief, ED-D
Kansas City 64106
ATTN: Chief, Engr Div
Omaha 68102
ATTN: Chief, Engr Div
New Orleans 70160
ATTN: Chief, LMED-DG
Little Rock 42203
ATTN: Chief, Engr Div
Tulsa 74102
ATTN: Chief, Engr Div
Ft. Worth 76102
ATTN: Chief, SWFED-D
ATTN: Chief, SWFED-F
Galveston 77550
ATTN: Chief, SWGAS-L
ATTN: Chief, SWGCO-C
ATTN: Chief, SWGED-DC
Albuquerque 87103
ATTN: Chief, Engr Div
Los Angeles 90053
ATTN: Chief, SPLED-F
San Francisco 94105
ATTN: Chief, Engr Div
Sacramento 95814
ATTN: Chief, SPKED-D
ATTN: Chief, SPKCO-C
Far East 96301
ATTN: Chief, Engr Div

US Army Engineer District
Portland 97208
ATTN: Chief, DB-6
ATTN: Chief, FM-1
ATTN: Chief, FM-2
Seattle 98124
ATTN: Chief, NPSCD
ATTN: Chief, NPSEN-FM
ATTN: Chief, EN-DB-ST
Walla Walla 99362
ATTN: Chief, Engr Div
Alaska 99501
ATTN: Chief, NPASA-R

US Army Engineer Division
New England 02154
ATTN: Chief, MEDED-T
ATTN: Laboratory
ATTN: Chief, MEDCD
Middle East (Rear) 22601
ATTN: Chief, MEDED-T
North Atlantic 10007
ATTN: Chief, NAEEN
South Atlantic 30303
ATTN: Laboratory
ATTN: Chief, SAEEN-TC
ATTN: Chief, SAEEN-TS
Huntsville 35807
ATTN: Chief, HNEED-CS
ATTN: Chief, HNEED-M
ATTN: Chief, HNEED-SR
Lower Mississippi 39180
ATTN: Chief, LMVED-G
Ohio River 45201
ATTN: Laboratory
ATTN: Chief, Engr Div
Missouri River 68101
ATTN: Chief, MRDED-G
ATTN: Laboratory
Southwestern 75202
ATTN: Laboratory
ATTN: Chief, SWDED-MA
ATTN: Chief, SWDED-TG
South Pacific 94111
ATTN: Laboratory
Pacific Ocean 96858
ATTN: Chief, Engr Div
ATTN: FMAS Branch
ATTN: Chief, POED-D
North Pacific 97208
ATTN: Laboratory
ATTN: Chief, Engr Div

6th US Army 94129
ATTN: AFKC-EN

7th US Army 09407
ATTN: AETTM-HRD-EMO

HQ, Combined Field Army (ROK/US) 96358
ATTN: CFAR-EN

US Army Foreign Science and
Tech Center
ATTN: Charlottesville, VA 22901
ATTN: Far East Office 96328

USA ARRAADCOM 07801
ATTN: ORDAR-LCA-OK

West Point, NY 10996
ATTN: Dept of Mechanics
ATTN: Library

Ft. Belvoir, VA 22060
ATTN: ATSE-TD-TL (2)
ATTN: Learning Resource Center
ATTN: British Liaison Officer (5)

Ft. Benning, GA 31905
ATTN: ATZB-FE-EP
ATTN: ATZB-FE-BG

Ft. Clayton Canal Zone 34004
ATTN: DFAE

Ft. Leavenworth, KS 66027
ATTN: ATZLCA-SA

Ft. Lee, VA 23801
ATTN: ORXMC-D (2)

Ft. McPherson, GA 30330
ATTN: AFEN-CD

Ft. Monroe, VA 23651
ATTN: ATEN-AD (3)
ATTN: ATEN-FE-ME
ATTN: ATEN-FE-BG (2)

Ft. Richardson, AK 99505
ATTN: AFZT-FE-E

Rocky Mountain Arsenal 80022
ATTN: SARRM-CO-FEP

USA-WES 39180
ATTN: C/Structures
ATTN: Soils & Pavements Lab

Naval Facilities Engr Command 22332
ATTN: Code 04
ATTN: Code 2013 C

Port Hueneme, CA 93043
ATTN: Merrill Library

Commander (Code 2636) 93555
Naval Weapons Center

Bolling AFB, DC 20332
AF/LEEEU

Little Rock AFB
ATTN: 314/DEEE

Patrick AFB, FL 32925
ATTN: XRQ

Tinker AFB, OK 73145
2854 ABG/DEEE

Tyndall AFB, FL 32403
AFESC/TST

Airports and Const Services Dir
Technical Info Reference Center
Ottawa, Ontario, Canada K1A 0M8

Bldg Research Advisory Board 20418
Federal Aviation Administration 20540
Dept of Transportation Library 20590
Transportation Research Board 20418

Division of Building Research
National Research Council
Ottawa, Ontario, Canada K1A 0R6

National Defense Headquarters
Director General of Construction
Ottawa, Ontario, Canada K1A 0K2

Commanding General, Marine Corps Base
ATTN: Mr. M. Rekdahl
Camp Pendleton, CA 92055

Commanding Officer
ATTN: Mr. L. Lindamood
Marine Corps Air Station
Yuma, AZ 85364

Commanding Officer
ATTN: Ensign Jerry Richardson
Naval Air Station
Alameda, CA 94501

Commanding Officer
ATTN: Mr. Dick Gould
Naval Air Station
Brunswick, ME 04011

Commanding Officer
ATTN: Mr. Bill Wilson
Naval Air Station
Cecil Field, FL 32215

Commanding Officer
ATTN: LT J. M. Cain
Naval Air Station
Norfolk, VA 23511

Commanding Officer
ATTN: Mr. Larry Lind
Naval Air Station
North Island
San Diego, CA 92135

Commanding Officer
ATTN: Mr. Rocco Stella
Naval Air Station
Willow Grove, PA 19090

Commanding Officer
ATTN: Mr. Mike Murphy
Naval Submarine Base, New London
Box 00
Groton, CT 06340

Commander
ATTN: Mr. Jerry Brooks
Naval Weapons Center
China Lake, CA 93555

Commanding Officer
ATTN: Mr. Dave Lovett
Engineering Div. Public Works Dept.
Naval Weapons Station
Charleston, SC 29408

Naval Facilities Engineering Command
Western Division
ATTN: Mr. Dave Brown, Code 405
P.O. Box 727
San Bruno, CA 94066

Commanding Officer
ATTN: Mr. Clyde Bradley
Naval Station
Mayport, FL 32228

Chairman
DOD Explosives Safety Board
2461 Eisenhower Ave.
Alexandria, VA 22331

Mr. H. Nickerson, FAC-0452D
Naval Facilities Engineering Command
200 Stovall Street
Alexandria, VA 22332

Mr. Joseph V. Tyrell, FAC-045
Naval Facilities Engineering Command
200 Stovall Street
Alexandria, VA 22332

Mr. P. H. Cave, FAC-032F
Naval Facilities Engineering Command
200 Stovall Street
Alexandria, VA 22332

Mr. R. A. Boettcher, L-03B
Naval Civil Engineering Laboratory
Port Hueneme, California 93043

Kanarowski, Stanley M.

Investigation of materials for waterproofing leaky corrugated galvanized steel arch magazines from the inside. -- Champaign, IL : Construction Engineering Research Laboratory ; available from NTIS, 1982. 43 p. (Technical report ; M-312)

1. Waterproofing. 2. Bunkers. I. Title. II. Series : U.S. Army. Construction Engineering Research Laboratory. Technical report ; M-312.